

## 84331103 / K31S10A: Cable-mounted Connector

### Assembly Instructions:

- Select cable size—see chart at right.
- Strip length:  
Outer jacket: 35mm, Ground: 16mm, Line: 10mm, Neutral: 10mm
- Remove bottom shell of connector.
- Loosen nut and slide back shell onto cable.
- Connect wires to contact assembly per wiring diagram at right, complying with tightening torque figures in chart at right.
- Reassemble back shell to contact assembly. Turn contact assembly clockwise to lock. Tighten cable nut according to torque chart.

Torque	
Screw Terminals Nm. ft./lb.	Cable Nut ft./lb. in./lb.
1.0 0.7	5.0 4.0
5.0	3.0
35.4	

**Recommended Wire Size**

North American  
12AWG

**North American Wiring**

Black  
Green  
White  
Back View



100 Interpower Avenue  
Oskaloosa, IA 52577 (U.S.A.)  
Toll-free-telephone: (800)662-2290  
Toll-free FAX: (800) 645-5360