


84332205 **K32S20A:**
Cable-mounted Connector

Rev.11-24-2014

Assembly Instructions:

- Select cable size—see chart at right.
- Strip length:
 Outer jacket: 55mm, Ground: 17mm, Line: 15mm, Neutral: 15mm
- Remove bottom shell of connector.
- Loosen nut and slide back shell onto cable.
- Connect wires to contact assembly per wiring diagram at right, complying with tightening torque figures in chart at right.
- Reassemble back shell to contact assembly. Turn contact assembly clockwise to lock. Tighten cable nut according to torque chart.

Torque					
Screw Terminals			Cable Nut		
Nm.	ft./lb.	in./lb.	Nm.	ft./lb.	in./lb.
1.1	0.8	9.7	5.0	3.7	44.3
Recommended Wire Size					
North American			International		
10AWG			4.0mm ²		
North American Wiring			International Wiring		
<p>Back View</p>			<p>Back View</p>		



100 Interpower Avenue
 Oskaloosa, IA 52577 (U.S.A.)
 Toll-free telephone: (800)662-2290
 Toll-free FAX: (800) 845-5360