


K I T E M A R K L I C E N C E



No. KM 60192

Dongguan Cooper Electronics Co Ltd

Dongguan

BS 1362: 1972: General purpose fuse-links for domestic and similar purposes (primarily for use in plugs)		
Type	Rating	Report Number
TDC 180	02 A, 240 V, 50 Hz	2001-0228, 2001-0237 & 2003-0009
TDC 180	03 A, 240 V, 50 Hz	2001-0223, 2001-0229, 2001-0232 & 2003-0009
TDC 180	05 A, 240 V, 50 Hz	2001-0224, 2001-0233, 2002-0046 & 2003-0009
TDC 180	07 A, 240 V, 50 Hz	2001-0225, 2001-0234 & 2003-0009
TDC 180	10 A, 240 V, 50 Hz	2001-0226, 2001-0230, 2001-0231, 2001-0235 & 2003-0009
TDC 180	13 A, 240 V, 50 Hz	2001-0227, 2001-0447, 2001-0236 & 2003-0009

BS 1362: 1972: Lead-free* general purpose fuse-links for domestic and similar purposes (primarily for use in plugs)		
Type	Rating	Report Number
TDC 180	02 A, 240 V, 50 Hz	2001-0228, 2001-0237 & 2003-0009
TDC 180	03 A, 240 V, 50 Hz	2001-0223, 2001-0229, 2001-0232 & 2003-0009
TDC 180	05 A, 240 V, 50 Hz	2001-0224, 2001-0233, 2002-0046 & 2003-0009
TDC 180	07 A, 240 V, 50 Hz	20041030-03
TDC 180	10 A, 240 V, 50 Hz	20041030-02
TDC 180	13 A, 240 V, 50 Hz	20041030-01

Note: * As declared by manufacturer for Directive 2002/95/EC compliance

First granted: 24 Sep 2001

Date: 15 Dec 2004

Page: 2 of 3

The licence remains the property of BSI and shall be returned immediately upon request. This licence does not expire. To check its validity telephone +44 (0)1442 230442.

BSI is incorporated by Royal Charter

BSI
Product Services

BSI Product Services

Maylands Avenue, Hemel Hempstead, Hertfordshire HP2 4SQ United Kingdom

Tel: +44 (0)1442 230442 Website: www.bsi-global.com

BSI Group Headquarters: 389 Chiswick High Road, London W4 4AL Tel: +44 (0)208 996 9000

PS0270202/AP